# General instructions for cleaning and care

# no.61 Oiling of wood (description of method)

| cleaning system with treatment                       | :               | object          | date            |  |  |  |  |  |  |
|--|-----------------|-----------------|-----------------|--|--|--|--|--|--|
| initial cleaning of raw, untreated                   | d parquet a     | address         | customer        |  |  |  |  |  |  |
|  | room classi     | fication        | representative  |  |  |  |  |  |  |
| work process: select one work stage from each number |                 |                 |                 |  |  |  |  |  |  |
|  | recommendations | recommendations | recommendations |  |  |  |  |  |  |

| K I | cleaning method                  | recommendations * chemical products | dosage | * |   | recommendations<br>machine / tool                | comments   |  |
|-----|----------------------------------|-------------------------------------|--------|---|---|--|--|--|
| 1   | dusting<br>damp mopping          |                                     | uoougo | v | Masslinn 2000/Floorwit white                    |  |  |  |
|     | pore filling (only if necessary) |                                     |        |   |   |  |  |  |
| 2   | oiling                           | Leinol BW                           | 100%   |   | <b>Multi squeegee</b> /<br>Flat mop 50          |  | apply first layer<br>with care                               |  |
| 3   | drying                           |                                     |        |   |   |  | At least 1hour<br>one week is ideal.                         |  |
| 4   | oiling                           | Leinol NW                           | 100%   |   | <b>Multi squeegee</b> /<br>Flat mop 50          |  | 2nd coat let dry for<br>at least 1h, if<br>possible 3rd coat |  |
| 5   | drying                           |                                     |        |   |   |  | min 1 hour,<br>followed by fine<br>sanding                   |  |
| 6   | dry sanding                      |                                     |        |   |   | Monomatic HS /<br>Suction ring                   | change pad often   |  |
| 7   | dusting<br>damp mopping          |                                     |        | v | Masslinn 2000/Floorwit white<br>Multi squeegee/ | <b>Balit Varifix</b> /<br>Balit/                 |  |  |
| 8   | polishing, vacuum polishing      |                                     |        |   |   | Monomatic HS /<br>Suction ring<br>Monomatic DS / | after polishing  |  |

\* basic treatment / structure: B: coated / C: waxed / D: oiled / E: sealed / F: untreated / G: maintenance care product / P: polishing / S: structured / V: heavily soiled

#### before protective treatment: the floor must be perfectly stripped, thoroughly rinsed and completely dry! important: green and black pad on hard wood only

### General instructions for cleaning and care

| no.61 | Oiling of wood ( | (description of met | thod) |
|-------|------------------|---------------------|-------|
|-------|------------------|---------------------|-------|

oiling (6 - 8 times in first year, then as needed)

| wetrok |
|--------|
|--------|

date

customer

| work process: sele  | ct one work sta | age from each | number  |
|---------------------|-----------------|---------------|---------|
| Work process. Sere. |                 | ago nonn ouor | mannoon |

room algoalfigation

object

address

|    | process: select one work stage from | each nu                               | mber                                   | room classif | ication | l   | representative                                   |  |        |
|----|-------------------------------------|---------------------------------------|--|--------------|---------|---|--|--|--------|
| ₽, | cleaning method                     | freq<br>uenc                          | recommendations<br>* chemical products | dosage       | *       | recommendations<br>pad / brush / mop / cloth  | recommendations machine / tool                   | comments                                   |        |
| 1  | dusting<br>damp mopping             |                                       |  |              |         | Masslinn 2000/Floorwit white<br>Synthetic fur | <b>Balit Varifix</b> /<br>Balit/                 |  |        |
| 1  | dry vacuum cleaning                 |                                       |  |              | S       | Dust roller nozzle                            | <b>Monovac</b> /<br>Scuba                        |  |        |
| 1  | vacuum sweeping<br>sweeping         |                                       |  |              |         |   |  | large areas:<br>sweeping                   | 2<br>m |
|    | cleaning with maintenance           |                                       |  |              |         |   |  |  |        |
| 2  | oiling                              |                                       | Leinol NW                              | 100%         |         | <b>Multi squeegee</b> /<br>Flat mop 50        |  | apply first layer<br>with care             |        |
| 2  | spray cleaning<br>full spray        |                                       | Leinol NW                              | 25 - 50%     |         | Pad blue/<br>Pad red/                         | Monomatic DS /<br>Spray unit<br>Monomatic LS /   |  |        |
| 3  | drying                              | · · · · · · · · · · · · · · · · · · · |  |              |         |   |  | min 1 hour,<br>followed by fine<br>sanding |        |
| 4  | dry sanding                         |                                       |  |              |         | Pad red/<br>Pad blue/                         | Monomatic I /<br>Suction ring<br>Monomatic DS /  | change pad often                           |        |
| 5  | polishing, vacuum polishing         |                                       |  |              |         | Pad yellow/                                   | Monomatic HS /<br>Suction ring<br>Monomatic DS / | if needed                                  |        |

\* basic treatment / structure: B: coated / C: waxed / D: oiled / E: sealed / F: untreated / G: maintenance care product / P: polishing / S: structured / V: heavily soiled

before protective treatment: the floor must be perfectly stripped, thoroughly rinsed and completely dry! important:

# General instructions for cleaning and care





## Information about the flooring



Wetrok AG cannot accept any liability for damages due to improper use.
For security information, see the safety data sheet at www.wetrok.ch.
Wear protection: gloves, safety goggles, work clothes
Follow the information and remarks on the label, product data sheet and material safety data sheet.
The product data sheet describes the product and gives information about its application, storage. See www.wetrok.ch
The recommended colours of pad and brushes consist to the actual wWetrok product range
Follow the special cleaning and care instructions of the floor manufacturer
The cleaning and care instructions are recommendations and suggestions and apply to floorings in object quality.

#### Strong alkalines can destroy or discolour wood coverings. Use a special basic linoleum cleaner! Wood coverings are sensitive to abrasive pads and brushes.

Permanent exposure to moisture should be avoided with wood coverings. Mop as little as possible and wring out the mop thoroughly. Allow it to dry completely before applying a protective treatment! Allow longer drying times than for non-porous coverings such as PVC. Wear a protective mask when there are fine particles of wood dust in the air, for example when sanding or dry vacuuming.

Hardwoods (deciduous wood) such as oak, beech, ash, maple, walnut and acacia, or exotic woods, are processed into parquet. Softwoods (coniferous wood) such as spruce, fir and pine are mostly used in the manufacturing of floor boards (long tongue-and-groove boards). Humidity variations cause wood to shrink (dry out) or swell (exposure to moisture) and, possibly, warp (moisture).

Distinguishing feature: appearance of wood, dull sound when tapped.



Remove loose dirt before every cleaning, damp mop smooth floors and vacuum structured floors. Cleaning agents and surface treatments may alter the appearance and properties of a floor's surface.

Test on an inconspicuous spot to find which product is suitable for your requirements.

Test beforehand on an inconspicuous spot to see if the cleaning agent or surface treatment damages the floor.

Dirt-trapping zones, incl. dirt-trapping mats (Wetrok Gardamat) in the entrance, at least 7m long, greatly reduce the amount of dirt tracked into the building.

If you have any questions, please don't hesitate to contact us. For training courses, contact the Wetrok Academy, tel. +41 (0)43 255 51 43 or academy@wetrok.ch.

Wetrok AG Steinackerstrasse 62, CH-8302 Kloten, Tel +41 (0)43 255 51 51, info@wetrok.ch, www.wetrok.ch, www.wetrok.com